



outdoors were blocked by snow. Remedy. There is a secondary set of inside gymnasium entry/exit doors which was blocked (table, chair, sporting equipment, etc.). Also, the fire extinguisher located in this same area was only partially accessible due to how some sporting equipment is being stored. Please consult with the fire marshal as whether there is an accessibility requirement (clearance around) for fire extinguishers and whether the gymnasium's second set of inside entry/exit doors is considered a fire exit.

**Special Notes and Action Required:**

Within the next 30 days, please forward an email to licensing indicating the fire marshal's response to the above items. Thank you.

---

If you feel something is unclear or unjustly cited, please contact me (phone 319-892-6827; email [alyons@dhs.state.ia.us](mailto:alyons@dhs.state.ia.us) <<mailto:alyons@dhs.state.ia.us>>) so that we may discuss the issue. If necessary, I can make a notation in your record. You may also send a letter that will be included in your licensing file noting any disagreement you may have with this report. If I have failed to provide for you any information discussed during my visit, please contact me and I will forward the information to you. Thank you.

**Consultant's Signature:**



**Date:**

02/12/2014